



**Firmware Release Note**

**P645R-A1**  
**Standard version**

**Release 3.40(GJ.4) C0**

**Date:**  
**Author:**

**April 12, 2004**  
**Richard**

# **ZyXEL P645R-A1 Standard version**

## **Release 3.40(GJ.4) C0**

### **Release Note**

**Date:** April 12, 2004

#### **Supported Platforms:**

Samsung 9847+9850+8951

#### **Versions:**

ZyNOS Version : V3.40(GJ.4) | 4/12/2004 17:32:57

Bootbase Version : V1.07 | 5/21/2003 22:07:38

#### **Notes:**

1. The P645R-A1 (ADSL Router) is a small-office and home device that will allow a small LAN to access the Internet. By integrating ADSL, and NAT capability, P645R-A1 provides not only the ease of installation and Internet access, but also the most completed security solution to protect your intranet and efficient network management for data traffic.

The P645R-A1 provides four single auto-sensing, auto-detection 10/100BASE-T Ethernet ports for connection to the user's local network, and a single RJ-11 port for connection to ADSL line.

Main features:

##### **- ADSL**

- Support Multi-Mode standard (ANSI T1.413, Issue 2 ; G.dmt(G.992.1); G.lite(G.992.2)).
- Auto-negotiating rate adaptation
- ADSL physical connection ATM AAL5 (ATM Adaptation Layer type 5)
- Support multi-protocol over AAL5 (RFC1483)
- Support PPP over ATM AAL5 (RFC2364)
- PPP over Ethernet support for DSL connection (RFC 2516)
- Support VC-based and LLC-based multiplexing
- F4/F5 OAM

##### **- Hardware**

- One 10/100M Ethernet UTP ports for LAN connection

##### **- Router**

- NAT (includes multi-to-multi NAT) / SUA
- Packet Filter
- VPN (IPSec, PPTP, & L2TP) pass through support
- Port forwarding
- Embedded Web Configuration
- SNMP v1 & v2c with MIB II
- 

#### **2. Modem code version: SAMSUNG, DSP Version 110.030909**

#### **3. Modem Setting :**

ADSL Standard	Multi
MinSNRMargin	6 db
TCM mode	ON
FEC R=2 mode	OFF

Tx Power attn	Normal db
---------------	-----------

## Known Issues:

1. When setting SMT menu4 "IP Address Assignment= Dynamic", into menu1.3 will show "IP Address Assignment = Static". It is not consistency each other.

## Features:

### Modification in 3.40(GJ.4)C0 (April 12,2004)

- 1 Change to FCS
- 2 Change default Rom file , change Menu 24.11 - Remote Management Control from All to Lan only

### Modification in 3.40(GJ.4) b2 (April 5,2004)

- 1.[BUG FIXED]  
Symptom: In eWC ping illegal url will get a success feedback  
Condition: ping illegal url In eWC ,on conditions that you can ping success with wan port.
- 2.[BUG FIXED]  
Symptom: the system occur exception  
Condition: In eWC ping character is longer than 32 bytes
- 3.[BUG FIXED]  
Symptom: The system occur exception  
Condition: we change Remote management Telnet Access Status field in eWC/Remote management/Telnet like "All" change to "LAN only" , "LAN only" change to "WAN only".
- 4.[BUG FIXD]  
Symptom: it will show error message(ip format error) In eWC  
Condition: you select In eWC Advanced Setup/ NAT/Full Feature /Edit Details/Rule1(n) /type one-to-one Click Local end ip field ,this error message will show
- 5.[BUG FIXED]  
Symptom: unix log can't be sent out  
Condition: In smt 24-3-2 set unix trace log active.
- 6.[BUG FIXED]  
Symptom : system will run into wrong state and won't process it  
Condition : If there is a second CHAP challenge packet incoming, system will run into wrong state and won't process it

### Modification in 3.40(GJ.4) b1 (Mar 15,2004)

- 1.[Bug fixed]  
Symptom: Setting PPPoe User name and password.  
Condition: When set NULL to User name and Pass word in SMT4, in eWC you will see a space on both user name and pass word filed.

### Modification in 3.40(GJ.3)C0(Mar 5, 2004)

- 1 Change to FCS.

### Modification in 3.40(GJ.3)b4(February 20, 2004)

- 1.[BUG FIXED]  
Symptom: arp table could not age out. And ping failed  
Condition: pc have same ip address as one of arp tables and different mac address
- 2.[BUG FIXED]  
Symptom: icmp ping time to exceed when NAT off.  
Conditon: the first icmp packet's ttl be always equal to zero. this makes time to exceed.

### Modification in 3.40(GJ.3)b3 (October 2, 2003)

1. Update DSP code to 110.030909 to fix the problem of ECI DSLAM and IES-1000.

2. [BUG FIXED]  
Symptom: The PPPoA connection trigger by Ethernet packet will fail, reset device can recover it.  
Condition: After several times of reboot.

**Modification in 3.40(GJ.3)b1 (July 18, 2003)**

1. [FEATURE ENHANCE] Add the SMT 24.10 - Time and Date Setting and SMT 24.11 - Remote Management.
2. [FEATURE ENHANCE] Reduce the F/W size by adjust the MMCT table and reduce HTP code size.
3. Update DSP code to 109.030508.
4. [BUG FIXED]  
Symptom: The “ping” and “tracert” confused when user tried to test many targets at the same time..  
Condition: In Routing, NAT mode.

**Modification in 3.40(GJ.2)b12 (May 23, 2003)**

1. [FEATURE ENHANCE] Add the CI command for the request of TE to decrease the test period.
2. [BUG FIXED]  
Symptom: The service provider default set to [WWW.DDNS.ORG](http://WWW.DDNS.ORG) not [WWW.DynDNS.ORG](http://WWW.DynDNS.ORG). The default setting should be [WWW.DynDNS.ORG](http://WWW.DynDNS.ORG).  
Condition: In the SMT and Web Configurator..

**Modification in 3.40(GJ.2)b11 (May 22, 2003)**

1. Update S5N8950 ADSL Debug Information to version 4.01.
2. Performance enhanced (about 20% in throughput test) by decrease SDRAM delay timer.  
Please also upgrade Bootbase to GJ1.07 when upgrade Ras to 3.40(GJ.2)b11.

**Modification in 3.40(GJ.2)b10 (May 12, 2003)**

1. Change the default setting to ENET ENCAP from PPPoE.
2. Change ARM MAC Rx/Tx buffer descriptor number to 64 from 60.
3. Change ARM MAC Rx/Tx buffer descriptor start address to 8-bit alignment.
4. [BUG FIXED] Merge the bug fixed from trunk 3.40.
5. [BUG FIXED]  
Symptom: Press 13/14 in main menu, the system will accept under SMT & Telnet.  
Condition:

**Modification in 3.40(GJ.2)b9 (May 08, 2003)**

1. Change the default setting to PPPoE from ENET ENCAP.

**Modification in 3.40(GJ.2)b8 (February 28, 2003)**

1. [BUG FIXED]  
Symptom: It's hard to link up with Siemens TI DSLAM in TianJin.  
Condition: S5N8950 got some noise in the handshake state.

**Modification in 3.40(GJ.2)b4 (January 15, 2003)**

1. [BUG FIXED]  
Symptom: System can't receive the correct the VC through SAR  
Condition: Happens only when configuring multiple PVC in bridge mode.
2. [BUG FIXED]  
Symptom: Upstream rate will not change if the link rate changed to higher from lower.  
Condition: Happens only when link rate changed from lower to higher.
3. [BUG FIXED]  
Symptom: Upstream will stop if the AX4000 bi-direction stress test.  
Condition: Happens only when configuring multiple PVC in bridge mode.
4. [BUG FIXED]  
Symptom: S5N8950 TC Upstream will stop if the AX4000 bi-direction stress test, but the S5N8947 SAR

still works.

Condition: Happens only when configuring multiple PVC in bridge mode.

**Modification in 3.40(GJ.1)b3**

1. Change DSP code to version 109.151220.

**Modification in 3.40(GJ.1)b2 (Nov 28, 2002)**

1. Change DSP code to version 109.021203.