Firmware 3.32A07

Infortrend®

New Release and Update Information

Date: April 21, 2004

Firmware Core: 3.32A07

Compatible RAIDWatch version: 1.54

Software updates are available at ftp.infortrend.com.tw/RAIDWatch/1.54

1. Overview

New features:

No new features added to this revision. This revision aims to solve some known issues.

2. Applicable Products

Firmware 3.34A06 is applicable to the following subsystem:

Models
IFT-6330-12U3D (7250F-12U3D)
IFT-6330-12F2D (7250F-12F2D)
IFT-6330-8U3D (7250F-8U3D)
IFT-6330-8F2D (7250F-8F2D)
IFT-6230-8U3D (7250F-8U3D)

3. List of Problems Fixed

1. Incorrect temperature data

   Fixed the bug that causes both LCD and terminal utility to display incorrect temperature readings.

2. Controller abnormal reset

   Fixed the bug that causes the controller to reset when using LCD keypad panel to scan in new hard drives.

3. Incorrect display of logical drive ID

   Fixed the bug that causes incongruous display of device message between LCD and terminal screen when displaying the following messages: LCD displays "Power Supply status: failed"; while the terminal interface displays "No Peripheral Device".