ZyXEL Prestige 128L

PreZyNOS v1.53(L.00) | 10/27/2000

Release Notes / Manual Supplement

Date: October 27, 2000

This document describes the enhancements in the ZyXEL Prestige product line since the last manual printing. The bug fixes section describes problems corrected since version 1.52.

Bug fixes

Ver 1.53(L.00)

1. Fix bug that the routing table disappears sometimes and causes it fails to work.
2. Add bandwidth management with P1600.

Known Problem List

1. Prestige has problems to support Unix remote commands (rlogin, rcp, and rsh) in SUA case.

To Upgrade Prestige

Get the files from ZyXEL anonymous FTP server (ftp.zyxel.com). Upgrade your Prestige by following the instructions for your model:

```
Versions:
        RAS F/W Version  -      V1.53(L.00)  10/27/2000
        ISDN F/W Version -      DSS1: V 085

RAS and ISDN firmware file:
        p128l.bin ( for Prestige 128L )

Commands:
        ATBAx:  Where x = baud rate
                options available are:
                        1= 38.4K
                        2= 19.2K
                        3= 9.6K
                        4= 57.6K
                        5= 115.2K
        ATUR:  Upload Firmware file via XMODEM

Romfile:  romfile0
        ATUR3:  Upload Romfile and clear all settings
                Note:  You don't need to upload this file if you are upgrading from release
                1.2(b.01) unless you want to reset all configurations to factory default.
```