ZyXEL

Firmware Release Note

P2000W_V2

Standard version

Release WV0004

Date: **April 14, 2006**
Author: **Lancy Wu**

ZyXEL P2000W_V2 Standard Version release WV0004 Release Note

Date: April 17, 2005

Supported Platforms:

ZyXEL P2000W_V2

Versions:

F/W Version : WV0004

Notes:

~~Known Issues:~~

Modifications in WV0001 | May 18, 2005
1   [Bug Fixed]
  1.1   SIP: The first invite include registation's authorization. (407)
  1.2   Add one switch to select provision service.
  1.3   Open admin account for provision.

Modifications in WV0001 | May 18, 2005
1   [Enhancement]
  1.1   Can input ":" in the user name.

Modifications in WV0001_T01 | July 27, 2005
2   [Bug Fixed]
  2.1   ASCII WEP key can't be used.
  2.2   Remove check H/W version, when user use P2000W_V2 earphone.

Modifications in WV0002 | August 01, 2005
3   [Bug Fixed]
  3.1   Add one space character in display name in SIP setting.
           Ex:From:123<sip:123@bcmcom.com>=> After: 123<sip:123@bcmcom.com>
  3.2   DTMF payload must be modify in sip signal, when we modify this payload in our web page.
  3.3   Modify SIP URI parameter(Freenet)
  3.4   Interoperability with T-online(Due to their system have two 183 packets).
  3.5   Remove check H/W version , when user use the earphone

Modifications in WV0003 | January 06, 2006
4   [Bug Fixed]
  4.1   Fix if FMTP has more than 1 our SIP parse wrong FMTP for DTMP relay. Because FMTP not only for DTMP so we must adjudge RTPMAP type is for telephone event or not.
  4.2   We won't make these commands "activate", "commit" after set default ATPM.
  4.3   Avoid the error when phone parses a unknown parameter.
  4.4   Avoid error display when phone is in ring state.
  4.5   Rename "Options Interval Timer" to "NAT Keep Alive" in Web.
  4.6   Disable the UPDATE_MENU page when the account "user" logins.
  4.7   For ZyXEL, change default DNS server IP from "168.95.1.1","139.175.55.244" to "192.168.0.4","192.168.0.5".
  4.8   Fix that phone can't stop to load default.
  4.9   Phone would lose the last "*" in phone number you want to call. And this "*" will show in the start of the next call.
  4.10   The VIA of response of 487 should be the same with that in invite message.
  4.11   Disable the function "BCM smart config". Because phone open 9090 port for this function.
  4.12   Avoid missing "Don't Disturb" item when phone get wrong earphone status.
  4.13   Modify the poweroff voltage from 3.6V to 3.45V.

Modifications in WV0004 | April 14, 2006
5   [Bug Fixed]
  5.1   Modify the icon of voice mail. Modify the icon of voice mail.
  5.2   Caller display implementation (if the display name contains "," it will show unavailable rather than number)
  5.3   Let phone can parse special characters on phonebook.
  5.4   IOP with nc=000001 on authentication parameters.
  5.5   Interoperability with option packet.